








1		1	7		2
2		1	8		2
3		1	9		1
4		1	10		2
5		1			
6		1			

A		M6X35mm	x26				
B		M6X16mm	x1				
C		M6	x5				
D		5#	x1				
E			x1				
F		M6X25mm	x4				
G		M6	x4				
H		4#	x1				
I		M6X40mm	x1				




STEP 1




CODE	HARDWARE	QTY
I	 M6X40mm	x1

STEP 2




CODE	HARDWARE	QTY
A	 M6X35mm	x5


STEP 3



STEP 4



STEP 5



STEP 6

